


INTERCONNECTIONS KIT, P/N 401460

- 1 401459 Quick connector on stand
- 1 101988-Z 1/8 in. stainless steel tubing (75 cm)
- 1 100319 1/8 in. swage x 1/8 in. NPT male adaptor
- 1 102116 Quick connector stem, 1/8 in. NPTF
- 1 102117 Quick connector stem, 1/4 in. NPTF
- 1 102184 Reducer, 1/4 in. swage x 1/8 in. swage



TO CONNECT TO THE PPC

- ❶ Screw the 1/8 in. swage x 1/8 in. NPT male adaptor into the PPC test port using teflon tape as a seal.
- ❷ Install reducer into quick connector on stand.
- ❸ Position quick connector on stand on bench or other stable surface. (Mounting is optional, holes are provided.)
- ❹ To connect PPC test port to the quick connect stand cut 1/8 in. SS tubing to desired length, bend as needed including 90° angle under reducer.



1/8 in. SS tubing can be bent by hand to desired shape but use caution not to kink the tube.

- ❺ Swage the 1/8 in. SS tube to adaptor on PPC and to reducer on quick connect stand.

PPC is a trademark, registered and otherwise, of DH Instruments, a Fluke Company